Notice

SANYO

	CTION CHANGE FORMATION	FILE NO.
Please add this notice to the Service M	anual listed below.	REVISION 1
Category: COLOR TELEVISION	Date: _J	ULY / 15 / 2006
Model: DP42746	Effective from : Chassi	is No. 42746-01
Destination: U.S.A. / CANADA	REF. No. SM780114	

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. 42746-00. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. 42746-00 used in Model DP42746 (SM780114).

Servicing should be performed by only trained and qualified service personnel.

1. IN THE CHASSIS ELECTRICAL PARTS LIST

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 19 Chassis Electrical A801 Parts List	_	Old	1AA0B10N2020A	ASSY, PWB, MAIN	1	YES	D
	New	1AA0B10N202AA	ASSY, PWB, MAIN	1	YES		
A600	A600	Old	1AA0B10N20300	ASSY, PWB, FILTER	1	YES	D
	7.000	New	1AA0B10N203A0	ASSY, PWB, FILTER	1	YES	D
Page 20 Chassis Electrical Parts List A1901 A1951	Old	1AA0B10N2020B	ASSY, PWB, CONTROL	1	YES	D	
	New	1AA0B10N202AB	ASSY, PWB, CONTROL	1	YES	D	
	A1951	Old	1AA0B10N2020C	ASSY, PWB, KEY_SW	1	NO	D
		New	1AA0B10N202AC	ASSY, PWB, KEY_SW	1	NO	

1. IN THE CHASSIS ELECTRICAL PARTS LIST (Cont.)

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
	A5500	Old	1AA0B10N20400	ASSY, PWB, DIGITAL	1	YES	D
		New	1AA0B10N204A0	ASSY, PWB, DIGITAL	1	YES	
Page 20 Chassis	EL901	Old	1AV4T44B01700	PDP MODULE / POWER	1	NO	D
Parts List	Liectrical	New	1AV4T44B01800	PDP MODULE / POWER	1	NO	
	U901	Old	1AV4U20C02100	UNIT, PDP-LOGIC	1	NO	D
		New	1AV4U20C07500	UNIT, PDP–LOGIC	1	NO	

2. IN THE CABINET PARTS LIST

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Key No.		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 21 Cabinet 2 Parts List	2	Old	1AV4Z12B38600	EL902 OPTICAL FILTER	1	NO	D
	New	1AV4Z12B42700	EL902 OPTICAL FILTER	1	NO		

For parts or service contact

Sanyo Manfacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

July 2006 SMC Published in U.S.A.